

July 26, 2001

Name & Department

Cims Number

ZONE MANAGERS

From - Name & Department

Cims Number

J. E. Hilger

Vice President, Global Service

485-03-06

Subject:

RAPID RESPONSE TRANSMITTAL # 01-009

41TE SOLENOID ASSEMBLY - 2002 CHRYSLER PT CRUISER

Approximately seventy six (76) vehicles were built and shipped with possible 41TE solenoid assemblies that may contain non-heat treated plungers. All vehicles will require solenoid assembly replacements. See attached VIN list.

The attached DMAIL will be sent to all affected Chrysler dealers later today requesting they change the solenoid assembly on vehicles listed. The dealerships receiving the DMAIL are the "ship to" dealerships and the VINS listed on their DMAIL are specific to their dealership.

Please assure that all zone personnel are aware of this information. If you have any questions, please contact Dan Krans in Dealer Technical Operations at T/L 754-2658.



J. E. Hilger

Attachment

DMAIL

July 26, 2001

TO: ALL AFFECTED CHRYSLER DEALERS
FROM: J. E. HILGER
SUBJECT: RAPID RESPONSE TRANSMITTAL #01-009
41TE SOLENOID ASSEMBLY

INVOLVED VEHICLES:
2002 Chrysler PT Cruiser

(Attach the "Ship To" Dealership's Specific VIN List Here)

SYMPTOM/CONDITION:
Some early built 2002 M.Y. vehicles were built and shipped with possible 41TE solenoid assemblies that may contain non-heat treated plungers.

PARTS REQUIRED:
1 05015646AC Solenoid Assembly

REPAIR PROCEDURE:
Replace the solenoid assembly as described in group 21 of the 2002 service information.

POLICY: Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:
Labor Operation No: 21-90-95-92 Solenoid Assembly Replace 0.9 Hrs.

FAILURE CODE: P8 - New Part

If you have any questions, contact your Zone service office.

J. E. Hilger
Vice President
Global Service

620953